

Notice of ScanSAR Products

Products with processing levels 1.5, 2.1, and 3.1 observed in ScanSAR mode may have nonuniformity in the radiance of the image.

Especially, unevenness of radiance are found more remarkably in the processing level 3.1 images.


We are currently doing to solve this issue.

Please note that when ordering products observed in ScanSAR mode.

IMG-HH-ALOS2100982750-160406-VBDR1.5GUD

HH L1.5


N



IMG-HH-ALOS2100982750-160406-VBDR2.1GUD

HH L2.1


N



IMG-HH-ALOS2100982750-160406-VBDR3.1GUD

Z


HH L3.1



IMG-HV-ALOS2100982750-160406-VBDR1.5GUD

N


HV L1.5



IMG-HV-ALOS2100982750-160406-VBDR2.1GUD

HV L2.1

N



IMG-HV-ALOS2100982750-160406-VBDR3.1GUD

HV L3.1

N

