



10.3 Comparison of GSMaP-version8 and rain-gauge data in Timor-Leste

YUKI OKADA¹ BENJAMIM HOPFFER MARTINS², NORITOSHI MAEHARA¹, FUMIKO FUKAYA¹

1:IDEA Consultants, Inc., Tokyo, Japan 2:Universidade Nacional Timor Lorosa'e



Fill Slope Failure



Bridge approach
was washed out



Heavy sedimentation
under bridge